

17514			OTV
ITEM	DADTNO	DECORIDEION	QTY.
NO.		DESCRIPTION	REQ'D
1	68356	Drive Cap (Black)	1
2	22958	Upper Housing Assembly - Black	1
3	27198	Motor Frame Clip	1
4	65828	Screw	1
5	22682	Switch and Circuit Board Assembly	1
6	27352	Field Assembly	1
7	65805	Brush Retaining Clip	2
8	64958	Insulator (CSA Only)	1
9		Hanger Bail	
9a	22267	(for units after 7/3/03)	1
9b	25061	(for units before 7/3/03)	1
10	64945	Rear Motor Frame	1
11		Lower Housing	
11a	65253	Lower Housing (AGC USA) - Black	1
11b	22848	Lower Housing (AGC CSA) - Black	1
12	64606	Front Housing Screw	2
13	S63897	Hinge Assembly	1
14	64537	Blade Lock	1
15	64535	Lock Keeper	1
16	27864	Blade Hinge Screw	2
17	27847	Carbon Brush w/ Shunt	2
18	64003	Blade Bracket	1
19	64139	Blade Screw	2

QTY. REQ'D
1
1
des #23a) USA 1
des #23b) CSA 1
sembly
ng Assy (USA) 1
ring Assy (CSA) 1
1
1
/ 1
2
2
1
1
2
1

IMPORTANT INFORMATION

When ordering repair parts, include part number, part name and model of trimmer. For best performance, trimmer blades should be CLEANED and OILED with Andis Clipper Oil before and after use, If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin, 53177 U.S.A.. Pack carefully, mail either Insured Parcel Post, or U.P.S., attach a letter to outside of package explaining difficulty.

FORM 12697 Rev-M Rev-M 1/13/14 SERVICE CENTER